



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
Report Date: April 4, 2007

Supervisor 1007

**Mine Name:** Bright 1 & 2

**Operator Name:** 3-H Landscape Products LLC

**Scott Holt**

2160 East Riverside Drive

St George, Utah 84790

**Inspector(s):** Doug Jensen, Daron Haddock

**Other Participants:** None

**Mine Status:** Active

**Permit number:** M/021/030

**Date:** February 12, 2007

**Time:** 1:50 PM

**Weather:** Clear, mild

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Inspected the quarries when in the area.

**Directions to Site:**

The mine is just south of SR 56 about six miles west of Beryl Junction. There is a hill south of the road called "The Point." Just east of The Point is a good dirt road that you follow south then west for about 1/4 mile to the north quarry and processing area. The road continues around another hill where there is another quarry and processing area.

**Inspection Summary:**

The four quarries within the permit are all still active. A loader and truck were operating in the first pit. An operator was greasing a loader near the other pits. There did not appear to be much change in the aerial extent of the pits from the previous inspection. No environmental concerns were noted.

**Conclusions and Recommendations:**

Should continue to monitor the site when in the area.

**Inspector's Signature**

dh:pb

cc:

3-H Landscape Products LLC

P:\GROUPS\MINERALS\WP\M021-Iron\M0210030-Bright1&2\Inspections\02122007insp.doc

**Date:**

4/4/07